



Dart Aerospace Ltd.
1270 Aberdeen St
Hawkesbury, ON
K6A 1K7
Canada

Tel (613) 632-5200
Fax 613 632-5246

D135-751-011
Job Sheet 200909



Part No: D135-751-011

Job Qty: 1 pcs

Part Name: Skidtube with Standard Wearplates Fits LH or RH



Part Weight: 0 lbs

Status: New

Priority: Medium

Job Created: 9/19/19

Job Tracking No:

Due Date: 10/16/19

Created By: Marie Lajeunesse

Type: SOLD

Description: ORDER 19679

Note: DWG DSI 9661 REV A, D3507 REV D IPP Rev:A 44353 New Issue JLM IPP Rev:B 06-12-18 As per Rev B JLM IPP Rev:C 07-12-11 ECN 1036 as per revB DD IPP Rev D 08.11.04 Added DT9431 to sequence 5 EC verf DD IPP Rev E 10.02.22 per PAR 09-043 EC verified: DD IPP Rev:F 10.06.09 remove seq110 DD verf:EC IPP Rev G 10.09.17 added D3507-1-bent EC verified:DD IPP REV:H 13.12.11 ECN13-619/ CHG002 DD VERF:JLM

Ship Via:

Bill of Materials

Job Routing

Op No	Operation	Qty	Start Date	Due Date	Standard		Workcenter/Supplier		Sign-off
					Setup Hrs	Run Hrs	Workcenter / Supplier	Lead Time	
120	Skidtubes - 1	1 pcs		10/16/19	0.00	0.80	Skidtubes - 1 - B4B		
							Skidtubes - 2 - B4B		
							Skidtubes - 3 - B4B		
							Skidtubes - 4 - B4B		
							Skidtubes - 5 - B4B		
							Skidtubes - 6 - B4B		
							Skidtubes - 7 - B4B		
140	QC 5	1 pcs		10/16/19	0.00	0.00	QC 5 - 10		
							QC 5 - 12		
							QC 5 - 17		
							QC 5 - 18		
							QC 5 - 19		
							QC 5 - 22		
							QC 5 - 24		
							QC 5 - 3		
							QC 5 - 43		
							QC 5 - 49		
							QC 5 - 51		
							QC 5 - 58		
							QC 5 - 68		
							QC 5 - 9		
							QC 5 - 50		
							QC 5 - 30		
							QC 5 - 40		
							QC 5 - 61		
							QC 5 - 81		
150	Handfinish - 1-1 Chemical-B4B	1 pcs		10/16/19	0.00	0.33	Handfinish - 1 - 1 - B4B		



Dart Aerospace Ltd.
1270 Aberdeen Street
Hawkesbury, ON K6A 1K7
CANADA
TEL.: 1 613 632-5200
Email: sales@dartaero.com
www.dartaerospace.com

Container No: S219258



Part: D135-751-011

Job No: 200909

Serial No/Batch: S219258

Revision:

Inspector:

Exp Date:

Instructions: FAA STC SR01709SE 18/10/17 TC LoA RDIMS

OCT 03 2019 63 9-89

Plex 9/19/19 9:36 AM Dart.lajeunesse.marie

				Handfinish - 1 - 2 - B4B	
				Handfinish - 1 - 3 - B4B	★ OCT 04 2019
				Handfinish - 1 - 4 - B4B	
				Handfinish - 1 - 5 - B4B	
				Handfinish - 1 - 6 - B4B	
				Handfinish - 1 - 7 - B4B	
				Handfinish - 1 - 8 - B4B	
				Handfinish - 1 - 9 - B4B	
				Handfinish - 1 - 10 - B4B	
				Handfinish - 1 - 11 - B4B	
				Handfinish - 1 - 12 - B4B	
				Handfinish - 1 - 13 - B4B	
				Handfinish - 1 - 14 - B4B	
				Handfinish - 1 - 15 - B4B	
				Handfinish - 1 - 16 - B4B	
				Handfinish - 1 - 17 - B4B	
				Handfinish - 1 - 18 - B4B	
				Handfinish - 1 - 19 - B4B	
				Handfinish - 1 - 20 - B4B	
				Handfinish - 1 - 21 - B4B	
				Handfinish - 1 - 22 - B4B	
160 QC 7	1 pcs	10/16/19	0.00 0.00	QC 7 - 10	
				QC 7 - 13	
				QC 7 - 14	
				QC 7 - 15	
				QC 7 - 17	
				QC 7 - 18	
				QC 7 - 19	
				QC 7 - 2	
				QC 7 - 28	
				QC 7 - 3	
				QC 7 - 30	
				QC 7 - 34	
				QC 7 - 36	
				QC 7 - 37	
				QC 7 - 41	
				QC 7 - 47	
				QC 7 - 48	
				QC 7 - 51	
				QC 7 - 58	
				QC 7 - 59	
				QC 7 - 60	

					QC 7 - 9	
					QC 7 - 68	
					QC 7 - 50	
					QC 7 - 67	
					QC 7 - 40	
					QC 7 - 24	
					QC 7 - 43	
					QC 7 - 61	
					QC 7 - 81	
					QC 7 - 76	79
170 Skidtubes - 2 - B4B	1 pcs	10/16/19	0.00 1.00	TF 1:20:00 24K18	Skidtubes - 1 - B4B	
					Skidtubes - 2 - B4B	
					Skidtubes - 3 - B4B	
					Skidtubes - 4 - B4B	TF
					Skidtubes - 5 - B4B	BE
					Skidtubes - 6 - B4B	
					Skidtubes - 7 - B4B	
180 QC 10	1 pcs	10/16/19	0.00 0.00		QC 10 - 10	
					QC 10 - 18	
					QC 10 - 24	
					QC 10 - 43	
					QC 10 - 50	
					QC 10 - 58	
					QC 10 - 9	
185 Handfinish - 6-1- Touch Up- B4B	1 pcs	10/16/19	0.00 0.10		Handfinish - 6 - 1 - B4B	
					Handfinish - 6 - 2 - B4B	
					Handfinish - 6 - 3 - B4B	
					Handfinish - 6 - 4 - B4B	
					Handfinish - 6 - 5 - B4B	
					Handfinish - 6 - 6 - B4B	
					Handfinish - 6 - 7 - B4B	
					Handfinish - 6 - 8 - B4B	
					Handfinish - 6 - 9 - B4B	
					Handfinish - 6 - 10 - B4B	BE B 19-10-18
					Handfinish - 6 - 11 - B4B	
					Handfinish - 6 - 12 - B4B	
					Handfinish - 6 - 13 - B4B	
					Handfinish - 6 - 14 - B4B	
					Handfinish - 6 - 15 - B4B	
					Handfinish - 6 - 16 - B4B	
					Handfinish - 6 - 17 - B4B	
					Handfinish - 6 - 18 - B4B	
					Handfinish - 6 - 19 - B4B	
					Handfinish - 6 - 20 -	

				B4B	
				Handfinish - 6 - 21 - B4B	
				Handfinish - 6 - 22 - B4B	
187 QC 7	1 pcs	10/16/19	0.00 0.00	QC 7 - 10	
				QC 7 - 13	
				QC 7 - 14	
				QC 7 - 15	
				QC 7 - 17	
				QC 7 - 18	BE
				QC 7 - 19	
				QC 7 - 2	
				QC 7 - 28	
				QC 7 - 3	
				QC 7 - 30	
				QC 7 - 34	
				QC 7 - 36	
				QC 7 - 37	
				QC 7 - 41	
				QC 7 - 47	
				QC 7 - 48	
				QC 7 - 51	
				QC 7 - 58	
				QC 7 - 59	
				QC 7 - 60	
				QC 7 - 9	
				QC 7 - 68	
				QC 7 - 50	
				QC 7 - 67	
				QC 7 - 40	
				QC 7 - 24	
				QC 7 - 43	
				QC 7 - 61	
				QC 7 - 81	
				QC 7 - 76	
190 Skidtubes - 3 - B4B	1 pcs	10/16/19	0.00 0.77	Skidtubes - 1 - B4B	
				Skidtubes - 2 - B4B	
				Skidtubes - 3 - B4B	
				Skidtubes - 4 - B4B	
				Skidtubes - 5 - B4B	BE
				Skidtubes - 6 - B4B	
				Skidtubes - 7 - B4B	
200 QC 5	1 pcs	10/16/19	0.00 0.00	QC 5 - 10	
				QC 5 - 12	
				QC 5 - 17	
				QC 5 - 18	
				QC 5 - 19	
				QC 5 - 22	
				QC 5 - 24	
				QC 5 - 3	
				QC 5 - 43	
				QC 5 - 49	
				QC 5 - 51	
				QC 5 - 58	
				QC 5 - 68	
				QC 5 - 9	
				QC 5 - 50	
				QC 5 - 30	

Plex 9/19/19 9:36 AM Dart.lajeunesse.marie

					QC 5 - 40	
					QC 5 - 61	
					QC 5 - 81	
210 Handfinish - 2-1 Pressure-B4B	1 pcs	10/16/19	0.00 0.08	Handfinish - 2 - 1 - B4B		
				Handfinish - 2 - 2 - B4B		41 OCT 16 2019
				Handfinish - 2 - 3 - B4B		
				Handfinish - 2 - 4 - B4B		DAS
220 Spray Paint - 2 - B4B	1 pcs	10/16/19	0.00 0.25	Spray Paint - 1 - B4B		41 OCT 16 2019
				Spray Paint - 2 - B4B		9-89
				Spray Paint - 3 - B4B		
				Spray Paint - 4 - B4B		
225 QC 14	1 pcs	10/16/19	0.00 0.00	QC 14 - 15		
				QC 14 - 2		
				QC 14 - 34		
				QC 14 - 41		
				QC 14 - 51		
				QC 14 - 58		
				QC 14 - 59		8 FEB 19 - 10 - 17
				QC 14 - 9		
				QC 14 - 68		
				QC 14 - 40		
				QC 14 - 19		
				QC 14 - 43		
				QC 14 - 24		
				QC 14 - 61		
				QC 14 - 81		
				260 Handfinish - 4-1-Assembly-B4B	1 pcs	10/16/19
Handfinish - 4 - 10 - B4B						
Handfinish - 4 - 11 - B4B						
Handfinish - 4 - 12 - B4B						
Handfinish - 4 - 13 - B4B						
Handfinish - 4 - 14 - B4B						
Handfinish - 4 - 15 - B4B						
Handfinish - 4 - 2 - B4B						
Handfinish - 4 - 3 - B4B						
Handfinish - 4 - 4 - B4B						
Handfinish - 4 - 5 - B4B						
Handfinish - 4 - 6 - B4B						
Handfinish - 4 - 7 - B4B						
Handfinish - 4 - 8 - B4B						
Handfinish - 4 - 9 - B4B						
270 QC 5	1 pcs	10/16/19	0.00 0.00			
				QC 5 - 12		
				QC 5 - 17		
					Plex 9/19/19 9:36 AM Dart.lajeunesse.marie	

DAS
59
9-89

						QC 5 - 18	
						QC 5 - 19	
						QC 5 - 22	
						QC 5 - 24	
						QC 5 - 3	
						QC 5 - 43	
						QC 5 - 49	
						QC 5 - 51	
						QC 5 - 58	
						QC 5 - 68	
						QC 5 - 9	
						QC 5 - 50	
						QC 5 - 30	
						QC 5 - 40	
						QC 5 - 61	
						QC 5 - 81	
280	Packaging 1-1 - Pick Kit - B4B	1	10/16/19	0.00	0.00	Packaging 1 - 1 - B4B	
	pcs					Packaging 1 - 2 - B4B	
						Packaging 1 - 3 - B4B	
						Packaging 1 - 4 - B4B	
						Packaging 1 - 5 - B4B	
						Packaging 1 - 6 - B4B	
						Packaging 1 - 7 - B4B	
						Packaging 1 - 8 - B4B	
						Packaging 1 - 9 - B4B	
						Packaging 1 - 10 - B4B	
						Packaging 1 - 11 - B4B	
						Packaging 1 - 12 - B4B	
						Packaging 1 - 13 - B4B	
						Packaging 1 - 14 - B4B	
						Packaging 1 - 15 - B4B	
						Packaging 1 - 16 - B4B	
						Packaging 1 - 17 - B4B	
						Packaging 1 - 18 - B4B	
						Packaging 1 - 19 - B4B	
						Packaging 1 - 20 - B4B	
						Packaging 1 - 21 - B4B	
						Packaging 1 - 22 - B4B	
						Packaging 1 - 23 - B4B	
						Packaging 1 - 24 - B4B	
						Packaging 1 - 25 - B4B	
						Packaging 1 - 26 - B4B	
						Packaging 1 - 27 - B4B	
						Packaging 1 - 28 - B4B	
						Packaging 1 - 29 - B4B	
						Packaging 1 - 30 - B4B	
						Packaging 1 - 31 - B4B	
						Packaging 1 - 32 - B4B	
						Packaging 1 - 33 - B4B	
						Packaging 1 - 34 - B4B	
						Packaging 1 - 35 - B4B	
						Packaging 1 - 36 - B4B	
290	QC 4	1	10/16/19	0.00	0.00	QC 4 - 28	
		pcs				QC 4 - 58	
						QC 4 - 69	
						QC 4 - 9	
						QC 4 - 46	
						QC 4 - 68	
						QC 4 - 72	

DAS
40
9-89

OCT 21 2019

PC

300	Packaging 3-1 - Stock - B4B	1 pcs	10/16/19	0.00 0.00	QC 4 - 74	DAS	OCT 22 2019
					QC 4 - 75	78 9-89	
					Packaging 3 - 1 - B4B		
					Packaging 3 - 2 - B4B		
					Packaging 3 - 3 - B4B		
					Packaging 3 - 4 - B4B		
					Packaging 3 - 5 - B4B		
					Packaging 3 - 6 - B4B		
					Packaging 3 - 7 - B4B		
					Packaging 3 - 8 - B4B		
					Packaging 3 - 9 - B4B		
					Packaging 3 - 10 - B4B		
					Packaging 3 - 11 - B4B		
					Packaging 3 - 12 - B4B		
					Packaging 3 - 13 - B4B		
					Packaging 3 - 14 - B4B		
					Packaging 3 - 15 - B4B		
					Packaging 3 - 16 - B4B		
					Packaging 3 - 17 - B4B		
					Packaging 3 - 18 - B4B		
					Packaging 3 - 19 - B4B		
					Packaging 3 - 20 - B4B		
					Packaging 3 - 21 - B4B		
					Packaging 3 - 22 - B4B		
					Packaging 3 - 23 - B4B		
					Packaging 3 - 24 - B4B		
					Packaging 3 - 25 - B4B	DAS 78 9-89	
					Packaging 3 - 26 - B4B		
					Packaging 3 - 27 - B4B		
					Packaging 3 - 28 - B4B		
					Packaging 3 - 29 - B4B		
					Packaging 3 - 30 - B4B		
					Packaging 3 - 31 - B4B		
					Packaging 3 - 32 - B4B		
					Packaging 3 - 33 - B4B		
					Packaging 3 - 34 - B4B		
					Packaging 3 - 35 - B4B		
					Packaging 3 - 36 - B4B	DAS 21 9-89	
305	DC - 1 - B4B	1 pcs	10/16/19	0.00 0.00	DC - 1 - B4B		OCT 22 2019
					DC - 2 - B4B		
310	QC 21 - FG	1 pcs	10/16/19	0.00 0.00	QC 21 - FG - 21		OCT 22 2019
					QC 21 - FG - 70		
					QC 21 - FG - 53	DAS 21 9-89	

Part Op 120 - 1-Cut Aft end as per dwg D3507 3-Drill Aft & Fwd Cap holes using DT8678 & DT8901 4-locate DT8870 & Drill
 Descriptions: Ground wire hole on top of Tube. 6-Locate DT8870 with #30 cleco in Ground wire hole ,then Pilot Drill all X-Bolt holes
 using #30" drill. ****DO NOT OPEN AFT CAP HOLES***** 7-Open crossbolt holes to 0.3125" (3 per side). Drill pilot holes
 for wearplates using Dt8868, Use DT8892 FOR REAR WEARPLATE HOLES. 8-Open six rear wearplate holes using
 DT8892. Open all wearplate holes to 0.297" 9-Open ground wire hole .297" section E-E 10-Open Aft & Fwd Cap holes
 using .208" drill. 11-Bore out aft end of tube as per Dwg D3507 & Detail "B". 12- Section G-G holes must be laid out
 manually, open to #30. 13-Deburr holes. *AK m136989*

140 - (QC5- Inspect part completeness to step on W/O)
 160 - (QC7-Inspect Chemical Conversion Coat)
 170 - 1-Open X-Bolt holes to .375"(1 Places) & .500"(2Places) as per Dwg D3507. and section G-G to .750" (2 places) 2-
 Counter Sink X-BOLT holes as per Dwg D3507 3-Deburr and blow out chips from inside of tube. 4-Bond web as per Dwg
 D3507 & QSI 015 start time : *10:00am Oct 8* end time: *10:45pm Oct 8* 5-Weld x-bolt spacers as per Dwg D3507
 and Detail C-C & D-D and G-G 7-Drill Rivet Holes as per Dwg D3507 Using Dt8871A&B 8-Deburr Rivet holes.
 180 - (QC10- Inspect visual per QSI004- ground welds)
 185 - (Touch up alodine) RE-ALODINE ONLY
 187 - (QC7-Inspect Chemical Conversion Coat)
 190 - 1-Rivet D3506-1/-3 as per Dwg D3507.
 200 - (QC5- Inspect part completeness to step on W/O)
 210 - Touch-up alodine tube as per QSI 005 section 4.1.2.1 do not acid etch.

220 - (Spray Paint / NDT Room) 1- Apply Primer as per QSI 005 4.2.1.3.3 and dwg A/R Primer
Batch: 5200299 2- Paint two coats of White paint as per QSI 005 4.2 and dwg A/R Paint

Batch: 5213125

225 - (QC14- Inspect Spray Paint)

260 - 1- Install Wearplate & Ground Wire inserts as per Dwg D3507. 1-Inspect for Foreign objects 2-Install Fwd & Aft caps as per Dwg D3507 And Detail "A" & "B" 3-Install Wearplates as per Dwg D3507 , Note:Install (1) Bolt and (1) washer on Ground Wire insert on top of tube Do not Install Screws where indicated on Dwg(Note #6) 4-assemble o'ring to plug as per dwg D3492 and apply o'ring lube 5- Wing Walk as per Dwg D3507 and QSI 005 4.4 Batch: _____

270 - (QC5- Inspect part completeness to step on W/O)

280 - (Pick Kit)

290 - (QC4- 100% Inspect kits for completeness)

300 - (Identify as per dwg & Stock Location: _____) Identify and pack for shipping as per PPP D135-751-011 PPP

Rev: _____

305 - Photocopy bluefile & type labels per PPP D135-751-011 CHG002

310 - QC21- Final Inspection - Work Order Release

012558

Job BOM

Part / Item	Component Name	Quantity	Operation	Container
D3507-1-BENT	Skidtube Assembly EC135	1 pcs (1 ea)	120-Skidtubes - 1	5166847
D3504-1	Crossbolt Spacer	2 pcs (2 ea)	170-Skidtubes - 2 - B4B	5146029
D3504-3	Crossbolt Spacer	1 pcs (1 ea)	170-Skidtubes - 2 - B4B	8105604
D3504-5	Crossbolt Spacer	2 pcs (2 ea)	170-Skidtubes - 2 - B4B	5091959
D3505-1	Web	1 pcs (1 ea)	170-Skidtubes - 2 - B4B	5154125
D3506-1	Doubler	4 pcs (4 ea)	190-Skidtubes - 3 - B4B	5149088
D3506-3	Doubler	2 pcs (2 ea)	190-Skidtubes - 3 - B4B	5154442
MS20601-AD4W3	Rivet	12 Ea (12 ea)	190-Skidtubes - 3 - B4B	5214592
ALS4-1032-225	Rivnut	1 Ea (1 ea)	260-Handfinish - 4-1-Assembly-B4B	5192155
ALS7-1032-130	Rivnut	38 Ea (38 ea)	260-Handfinish - 4-1-Assembly-B4B	5190021
AN3C4A	Bolt	31 Ea (31 ea)	260-Handfinish - 4-1-Assembly-B4B	5218780
AN3C5A	Bolt	2 Ea (2 ea)	260-Handfinish - 4-1-Assembly-B4B	5216219
AN526C1032R10	Screw	2 Ea (2 ea)	260-Handfinish - 4-1-Assembly-B4B	5166981
D2965	Cap	1 pcs (1 ea)	260-Handfinish - 4-1-Assembly-B4B	5166570
D2965-3	Cap	1 pcs (1 ea)	260-Handfinish - 4-1-Assembly-B4B	5166571
D3492-1	Plug	4 pcs (4 ea)	260-Handfinish - 4-1-Assembly-B4B	5204549
D3492-3	Plug	4 pcs (4 ea)	260-Handfinish - 4-1-Assembly-B4B	5215332
D3492-7	Plug	2 pcs (2 ea)	260-Handfinish - 4-1-Assembly-B4B	5148611
D4918-047	Wearplate Aft	1 pcs (1 ea)	260-Handfinish - 4-1-Assembly-B4B	5153202
D4918-1	Wearplate Fwd	1 pcs (1 ea)	260-Handfinish - 4-1-Assembly-B4B	5220080
D4918-3	Wearplate Center Fwd	1 pcs (1 ea)	260-Handfinish - 4-1-Assembly-B4B	5170023
D4918-5	Wearplate Center Aft	1 pcs (1 ea)	260-Handfinish - 4-1-Assembly-B4B	5170026
NAS1149C0332R	Washer (AN960C10L)	33 Ea (33 ea)	260-Handfinish - 4-1-Assembly-B4B	5218154
NAS1611-007	O-Ring	2 Ea (2 ea)	260-Handfinish - 4-1-Assembly-B4B	F103697
NAS1611-010	O-Ring	4 Ea (4 ea)	260-Handfinish - 4-1-Assembly-B4B	5057658
NAS1611-013	O-Ring	4 Ea (4 ea)	260-Handfinish - 4-1-Assembly-B4B	5217822
AN3C4A	Bolt	8 Ea (8 ea)	280-Packaging 1-1 - Pick Kit - B4B	5090638
D3512-041	Wearplate	2 pcs (2 ea)	280-Packaging 1-1 - Pick Kit - B4B	5220936
NAS1149C0332R	Washer (AN960C10L)	8 Ea (8 ea)	280-Packaging 1-1 - Pick Kit - B4B	5211568


M.U. 012470

Job Allocations				
Operation	Component Part	Required	Inventory	Allocated
120-Skidtubes - 1	D3507-1-BENT	1	10	0
	D3504-1	2	120	0
	D3504-3	1	103	0
	D3504-5	2	6	0
	D3505-1	1	10	0
170-Skidtubes - 2 - B4B	D3506-1	4	13	0
	D3506-3	2	16	0
	MS20601-AD4W3	12	333	0
	ALS4-1032-225	1	1,872	0
	ALS7-1032-130	38	1,652	0
190-Skidtubes - 3 - B4B	AN3C4A	31	584	0
	AN3C5A	2	680	0
	AN526C1032R10	2	57	0
	D2965	1	52	0
	D2965-3	1	45	0
260-Handfinish - 4-1-Assembly-B4B	D3492-1	4	92	0
	D3492-3	4	50	0
	D3492-7	2	14	0
	D4918-047	1	4	0
	D4918-1	1	0	0
	D4918-3	1	4	0
	D4918-5	1	4	0
	NAS1149C0332R	33	2,974	0
	NAS1611-007	2	232	0
	NAS1611-010	4	131	0
280-Packaging 1-1 - Pick Kit - B4B	NAS1611-013	4	128	0
	AN3C4A	8	584	0
	D3512-041	2	0	0
	NAS1149C0332R	8	2,974	0
Part Specifications				
Specifications could not be found.				


Plex 9/19/19 9:36 AM Dart.lajeunesse.marie

Qty	Part Number	Description
X	D3507-041	SKIDTUBE ASSEMBLY
1	D2962-150	EXTRUSION
1	D2965	CAP
1	D2965-3	CAP
4	D3482-041	PLUG ASSEMBLY
4	D3482-043	PLUG ASSEMBLY
2	D3482-047	PLUG ASSEMBLY
2	D3504-1	CROSS BOLT SPACER
1	D3504-3	CROSS BOLT SPACER
2	D3504-5	CROSS BOLT SPACER
1	D3505-1	WEB
4	D3506-1	DOUBLER
2	D3506-3	DOUBLER
1	D4918-1	WEARPLATE
1	D4918-3	WEARPLATE
1	D4918-5	WEARPLATE
1	D4918-047	WEARPLATE
38	AELS-1032-130	INSERT
1	AELS-1032-225	INSERT
31	AN3C4A	BOLT
2	AN3C5A	BOLT
2	AN526C1032-10	SCREW
33	AN960C10L	WASHER
12	MS20601AD4W3	RIVET


SHOP COPY
RETURN TO
ENGINEERING
UNCONTROLLED COPY
SUBJECT TO AMENDMENT
WITHOUT NOTICE
WORK ORDER
NO. 2009 09
MLJ
19-09-19



D3507-1 BENDING/CUTTING DETAIL



D3507-1 DRILLING DETAIL




DETAIL A
TYP. 6 PL
SCALE 3:10

GENERAL NOTES:


- 1) MATERIAL: N/A
- 2) FINISH: CHEMICAL CONVERSION COAT PER DART QSI 005 4.1 PRIOR TO INSERTING D3505-1 WEB.
STANDARD: PRIME (REF. 4.2.1.3.3) AND PAINT WHITE PER DART QSI 005 4.2.
OPTIONAL: POWDER COAT WHITE (REF 4.3.5.1) PER DART QSI 005 4.3.
BLACK ANTI-SKID PAINT AS INDICATED TO 1.00 ABOVE CENTERLINE PER DART QSI 005 4.4 (OPTIONAL)
- 3) TOLERANCES: PER DART QSI 018 UNLESS OTHERWISE NOTED
- 4) DIMENSIONS: INCHES UNLESS OTHERWISE NOTED
- 5) BREAK SHARP EDGES: 0.005 TO 0.010 MAX
- 6) IDENTIFICATION: IDENTIFY WITH DART B/N PER DART QSI 044 6.4 (VIBRATING STYLUS) ON I.D. OF TUBE
- 7) WEIGHT: 24.1 LB (FROM IIN-D135-751)
- 8) WELDING TO BE DONE PER DART QSI 004
- 9) INSERT D3505-1 WEB TO LOCATION SHOWN OFF AFT END OF SKIDTUBE AND BOND WEB INTO OUTER TUBE WITH NON-STRUCTURAL SIKAFLEX-241/291 ADHESIVE PER DART QSI 015 AFTER BENDING
- 10) USE DART DRILL TEMPLATE DT8868 TO LOCATE AND DRILL Ø0.297 HOLES (38 PLACES) FOR WEARSHOE INSERTS. INSTALL AELS-1032-130 PER SECTION C-C (38 PLACES) AFTER FINISH. SEAL WEARPLATE BOLTS WITH SIKAFLEX-241/291.
- 11) DO NOT INSTALL AN3C4A BOLTS AND AN960C10L WASHERS IN INDICATED LOCATIONS

D	REMOVE D3558-X GASKETS, D4918-X WAS D3508-X REVISE FINISH TO ADD PAINT AS THE PREFERRED FINISH. REVISED NOTES	DW	13.08.30
C	ADD D3504-5, FOR SKID GEAR DEFLECTOR; CHANGE FWD CAP BOLT TO AN526C1032-10 SCREW	DC	07.09.19
B	ADD GASKET, CHANGE HARDWARE MATL	PH	06.11.01
A	NEW ISSUE	PH	06.04.21
REV.	DESCRIPTION	BY	DATE
DESIGN	DW	DART AEROSPACE USA, INC KENT, WA	
DRAWN	DW		
CHECKED	UP	DRAWING NO.	REV. D
MFG. APPR.	AN	D3507	SHEET 1 OF 2
APPROVED	WJ	TITLE	SCALE
DE APPR.	WJ	EC 135 SKIDTUBE	NTS
DATE	13.08.30	COPYRIGHT © 2013 BY DART AEROSPACE USA, INC THIS DOCUMENT IS UNCLASSIFIED AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR REPRODUCED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE USA, INC.	




SECTION C-C
(SCALE 3:10)

- D3504-1 CROSS BOLT SPACER**
- AFTER BENDING AND DRILLING ASSEMBLY PERFORM THE FOLLOWING FOR Ø0.500 HOLES ONLY:
1. CHAMFER HOLE 0.030 x 45°
 2. INSERT D3504-1 CROSS BOLT SPACER 2 PL
 3. WELD INTO PLACE AND GRIND FLUSH
 4. IF REQUIRED, PASS Ø0.404 (1/4" DRILL) THRU HOLE
 5. INSTALL D3506-1 DOUBLER 4 PL USING MS20801AD4W3 RIVET 8 PL
 6. AFTER FINISH, INSTALL D3492-041 PLUG ASSEMBLY 4 PL




SECTION D-D
(SCALE 3:10)

- D3504-3 CROSS BOLT SPACER**
- AFTER BENDING AND DRILLING ASSEMBLY PERFORM THE FOLLOWING FOR Ø0.375 HOLES ONLY:
1. CHAMFER HOLE 0.030 x 45°
 2. INSERT D3504-3 CROSS BOLT SPACER 1 PL
 3. WELD INTO PLACE AND GRIND FLUSH
 4. IF REQUIRED, PASS Ø0.277 (1/4" DRILL) THRU HOLE
 5. INSTALL D3506-3 DOUBLER 2 PL USING MS20801AD4W3 RIVET 4 PL
 6. AFTER FINISH, INSTALL D3492-047 PLUG ASSEMBLY 2 PL






D3507-041 ASSEMBLY DETAIL



SECTION G-G
(SCALE 3:10)

- AFTER BENDING AND DRILLING PERFORM THE FOLLOWING FOR Ø0.750 HOLES ONLY:
1. CHAMFER HOLE 0.030 x 45°
 2. INSERT D3504-5 CROSS BOLT SPACER 2 PL
 3. WELD INTO PLACE AND GRIND FLUSH
 4. IF REQUIRED, PASS Ø0.594 (19/32 DRILL) THRU HOLE
 5. AFTER FINISH, INSTALL D3492-043 PLUG ASSEMBLY 4 PL



RELEASED
11 2013-12-10

DESIGN	DW	DART AEROSPACE USA, INC	
DRAWN	DW	KENT, WA	
CHECKED	GP	DRAWING NO.	REV. D
MFG. APPR.		D3507	SHEET 2 OF 2
APPROVED		TITLE	SCALE
DE APPR.		EC 135 SKIDTUBE	NTS
DATE	13.08.30	COPYRIGHT © 2013 BY DART AEROSPACE USA, INC THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMBINED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE USA, INC.	

5.0 PARTS LIST

Item	Qty -011	Qty -041	Qty -043	Qty -101	Part Number	Description
	X				D135-751-011	SKIDTUBE INSTALLATION
	1	X			D135-751-041	REPLACEMENT SKIDTUBE
			X		D135-751-043	WEARPLATE KIT
				X	D135-751-101	SKIDTUBE EXTENSION KIT
1		1			D3507-041	SKIDTUBE ASSEMBLY
2	4				**BRS8-96/48SZ-M8-W2	CLAMP
3	8				**LN9038-08032	SCREW
4		1			*D2965	CAP
5		1			*D2965-3	CAP
6		2			***AELS-1032-130	INSERT
7		2			***AELS-1032-225	INSERT
8		2			*AN3C5A	BOLT
9		2			*AN960C10L	WASHER
10		2			*AN526C1032-10	SCREW
20A		1	1		*D3508-1	WEARPLATE
20B		1	1		*D3558-1	GASKET
21A		1	1		*D3508-3	WEARPLATE
21B		1	1		*D3558-3	GASKET
22A		1	1		*D3508-5	WEARPLATE
22B		1	1		*D3558-5	GASKET
23A		1	1		*D3508-7	WEARPLATE
23B		1	1		*D3558-7	GASKET
24		38			*AELS-1032-130	INSERT
25	8	30	38		*AN3C4A	BOLT
26	8	30	38		*AN960C10L	WASHER
27	2		2		D3512-1	WEARPLATE
30		1			*AELS-1032-225	INSERT
31		1			*AN3C4A	BOLT
32		1			*AN960C10L	WASHER
40		4			*D3492-041	PLUG ASSEMBLY
41		4			***NAS1611-010	O-RING
42		2			*D3492-047	PLUG ASSEMBLY
43		2			***NAS1611-007	O-RING
44		4			*D3506-1	DOUBLER
45		8			*MS20601AD4W3	RIVET
46		2			*D3506-3	DOUBLER
47		4			*MS20601AD4W3	RIVET
48		4			*D3492-043	PLUG ASSEMBLY
49		4			***NAS1611-013	O-RING
50				1	D3510-041	INSERT ASSEMBLY
51				2	***AELS-1032-130	INSERT
52				6	***AELS-1032-225	INSERT
53				2	***ALS4-428-165	INSERT
54				2	AN4C7A	BOLT
55				2	AN960C416L	WASHER
56				2	AN3C4A	BOLT
57				8	AN3C7A	BOLT
58				10	AN960C10L	WASHER

* PART IS INCLUDED WITH D3507-041 SKIDTUBE ASSEMBLY

** TO BE SUPPLIED BY CUSTOMER, LISTED AS REFERENCE ONLY

*** DENOTES PART IS INCLUDED WITH ASSEMBLY ABOVE

• COPYRIGHT © 2006 BY DART AEROSPACE USA, INC. •

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE USA, INC.

Revision: C

Date: 07.09.20

Entered: _____ Date: _____



WORK ORDER NON-CONFORMANCE / ROUTE UPDATE

NCR No. _____

Route update only ☐

Job: _____ Part No. _____	DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐	DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Eng. (Non-AW) ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Engineering ☐ Water Jet ☐ Supplier ☐ Quality ☐			
Date :	Sequence #:	QTY Affected :		MRB (QS1042)	
Description Work Order Deviation		Disposition		Completed By	
				Lead hand / Supervisor	
				QC / QA Coordinator	
Root Cause Operator ☐ Manufacturing Process ☐ Equip/Tooling ☐ Handling/Presservation ☐ Material ☐ Product Improvement ☐ Process Improvement ☐ Human Factors ☐ ☐ Pressure/Forced ☐ Bending ☐ Crushing ☐ Cracks ☐ Crimp/Kink/Ripple/Wave/Twist ☐ Marks/Chatter ☐ Mislabeled		FAULT CATEGORY ☐ Contamination ☐ Misaligned/off center ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Incomplete/Unclear Instructions ☐ Drill Holes ☐ Fit/Function ☐ Power Loss/Surge ☐ Folio/Program ☐ Grain Direction ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set/Set-up ☐ Positioned Wrong ☐ Outside Tolerance ☐ Drawing ☐ Finish ☐ Part Lost/Missing ☐ Misread			
Other/Details:					

2.18

11.22-1200 - 33
12.33 - 218 - 2.09
~~1.46~~ 1.46
7.28 45